

Exploded view of the carburetor used on the Consul, Zephyr, and Zodiac before 1956.